

Wood Destroying Insect Inspection Report

Notice: Please read important consumer information on page 2.

Section I. General Information

Inspection Company, Address & Phone
Coastline Pest Control
605 Twin Tree Road
Salisbury, MD 21801
410-546-0111

Company's Business Lic. No.

28967

Date of Inspection

5/6/09

Address of Property Inspected

104 Middleneck Lane
Salisbury, Md 21804

Inspector or Authorized Signature - Print Inspector's Name - Certification/Credentialing # if applicable.

Structure(s) Inspected

Jack James

HOUSE

Section II. Inspection Findings This report is indicative of the condition of the above inspected structure(s) on the date of inspection and is not to be construed as a guarantee or warranty against latent, concealed, or future infestations or defects. Based on a careful visual inspection of the readily accessible areas of the structure(s) inspected:

- A. No Visible evidence of wood destroying insects was observed.
- B. Visible evidence of wood destroying insects was observed as follows: (See attached diagram)

1. Live insects (description & location):

2. Dead insects, parts, frass, shelter tubes, exit holes, or staining (description and location): **previous sub-terranean termites located in base to floor joists and bandboard**

3. Visible damage from wood destroying insects was noted as follows (description and location): **previous sub-terranean termites located in base to floor joists and bandboard. (SEE DIAGRAM)**

NOTE: This is not a structural damage report. If box B above is checked, it should be understood that some degree of damage, including hidden damage, may be present. If any questions arise regarding damage indicated by this report, it is recommended that the buyer or any interested parties contact a qualified structural professional to determine the extent of damage and the need for repairs. Maryland regulations require the inspector indicate, if known, whether the damage indicated by this report has, or will be, corrected or further evaluated. Unless disclosed in Section V, below, the inspector does not know the disposition of the listed damage.

Yes No It appears that the structure(s) or a portion thereof may have been previously treated. Evidence of possible previous treatment:

drill holes in block and floor joists

The inspecting company can give no assurances with regard to work done by other companies. The company that performed the treatment should be contacted for information on treatment and any warranty or service agreement which may be in place.

Section III. Recommendations/Treatment

No treatment recommended: (Explain if Box B in Section II is checked) **previously treated**

Recommend treatment for the control of:

Proper control measures were performed by this inspection company for insect evidence listed in Section II. B., above.

Section IV. Obstructions and Inaccessible Areas

The following areas of the structure(s) inspected were obstructed or inaccessible:

- Basement **7, 24**
- Crawlspace **7, 24**
- Main Level **1, 3, 4, 6, 7, 8, 9**
- Attic **11**
- Garage
- Exterior **17**
- Porch
- Other

The inspector may write out obstructions or use the following optional key:

- | | |
|-------------------------|--|
| 1. Fixed ceiling | 13. Only visual access |
| 2. Suspended ceiling | 14. Cluttered condition |
| 3. Fixed wall covering | 15. Standing water |
| 4. Floor covering | 16. Dense vegetation |
| 5. Insulation | 17. Exterior coverings |
| 6. Cabinets or shelving | 18. Window well covers |
| 7. Stored items | 19. Wood pile |
| 8. Furnishings | 20. Snow |
| 9. Appliances | 21. Unsafe conditions |
| 10. No access or entry | 22. Rigid foam board |
| 11. Limited access | 23. Synthetic stucco |
| 12. No access beneath | 24. Duct work, plumbing, and/or wiring |

Section V. Additional Comments and Attachments (these are an integral part of the report)

Attachments

Signature of Seller(s) or Owner(s) if refinancing. Seller acknowledges that all information regarding W.D.I. infestation, damage, repair, and treatment history has been disclosed to the buyer.

Print name of Property Owner/Seller:

Signature of Buyer. The undersigned hereby acknowledges receipt of a copy of both page 1 and page 2 of this report and understands the information reported.

Graph

ADDRESS:

164 middle neck LN.
Salisbury, Md 21804

